

Message

---

**From:** Ketellapper, Victor [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=DC60D6FD9A99422D902FC8AE9980C4C6-KETELLAPPER, VICTOR]  
**Sent:** 11/8/2019 2:54:56 PM  
**To:** Mahmud, Shahid [Mahmud.Shahid@epa.gov]  
**Subject:** Darrow, Freezeout, and Triangle Abandoned Uranium Mine SI  
**Attachments:** DFT SI Fact Scheet.pdf; DFT PA Fact Sheet.pdf

Shahid,

Dania stopped by my office yesterday and told me you were interested in learning about the Preliminary Assessment (PA) and Site Inspection (SI) that was completed at the Darrow Freezeout and Triangle Abandoned Uranium Mines in South Dakota. I have attached the two fact sheets that discuss the results of the PA and discusses the planned SI.

Contact me if you have questions regarding this site.

Victor

Victor Ketellapper, PE  
Team Leader, Site Assessment Program  
USEPA Region 8 - Superfund and Emergency Management Division  
Phone 303-312-6578